

SECRET

20 September 1971

MEMORANDUM FOR: Deputy for Operations, OSA

SUBJECT: U-2R 055 Incident, 13 Sep 71

- 1. In reviewing the above incident, the following comments/opinions are submitted:
 - a. Ref report, page 1. Although agreed it was an early hour, it still seems the specialized aircrew briefing should have been done the day of the flight. In the least, a review of the previous day's briefing.
 - b. Ref report, page 6. The T-33 accident on 11 Aug was not included. Apparently did not consider the 11 Aug accident as a flight, per se. With the outcome being a major aircraft accident, a summary should have been included in this report.
 - c. The following is my opinion only. Prior to the approach for the landing that produced the incident, some discussion occurred concerning fuel unbalance. Fuel was transferred for from $1\ 1/2$ to 2 minutes or longer. The fuel transfer rate is 6-8 gal per minute. I would have expected the IP to confirm another fuel balance check prior to an attempted landing.
- 2. Since corrective action has been completed, suggest the incident be closed.

Safety Officer \

CONCUR:

SECRET

25X1A

25X1A

25X1A